



**EDUCATION DEPARTMENT
GOVERNMENT OF SIKKIM
NAMCHI**

Memo No. 1249/AE/EDN/(S)/2023/626

Date 26/02/24

BUILDING SAFETY CERTIFICATE

- A) Name of School/ Institution: Government Secondary School Chuba
B) Location: Chuba
C) District: Namchi.
D) Type of School: Government
E) Number of Structure: 03
F) Type of Structure: 1- 6/R/S/B, 2- 4/R/S/B
G) No. of Doors in a Classroom: 01
H) No. of Fire Extinguisher: 04
I) Availability of Access for differently abled person: Yes
J) Boundary Fencing: No

REMARKS: During physical verification, the structures appeared safe. However, in order to ensure the safety of the structure, detailed structural analysis has to be done to check the stability of the structure.

This safety Certificate shall become invalid in the case of any alteration done to the structure.


Junior Engineer,
Education Department,
Namchi District.


Assistant Engineer,
Education Department,
Namchi District.